














## Smith Style Tips



	<b>SFS</b>	Fine Spline	000-9
	<b>MCFS</b>	Fine Spline	000-3
	<b>SFSH</b>	Fine Spline High Speed	000-4
	<b>SFSHS</b>	Fine Spline High Speed Stainless Insert	0-7
	<b>S-SS-RIP</b>	Mach 1 Ripper Bevel & Scrap Cutting	4,6,8,10
	<b>SHT</b>	Heating Tip	
	<b>SGFB</b>	Bent Gouger	2,4,6,8
	<b>SPRB</b>	Rivet Bulkhead Gouger	1-5

## Victor Style Tips



	<b>2VFS</b>	Fine Spline	0000-9
	<b>2VFSH</b>	Fine Spline High Speed	000-7
	<b>2VFSHS</b>	Fine Spline High Speed Stainless Insert	00-8
	<b>V-SS-RIP</b>	Mach 1 Ripper Bevel & Scrap Cutting	4,6,8,10
	<b>VHT</b>	Heating Tip	
	<b>VGFB</b>	Bent Gouger	2,4,6,8
	<b>VPRB</b>	Rivet Bulkhead Gouger	1-5
	<b>3VFS</b>	Fine Spline High Speed 3 Series	000-4
	<b>3VFSH</b>	Fine Spline High Speed 3 Series	000-4
	<b>3VHT</b>	Heating Tip 3 Series	
	<b>3VGFB</b>	Bent Gouger 3 Series	000-4