· · · Accessories

Engine Drive Accessories

Also see Trailers on page 129.

Big Blue Accessories



Cable Holder 043946For Big Blue 500 Pro/600 Series/800 Series.



Vandalism Lockout Kit 399802 Field

For Big Blue 500 Pro/600 Series. Lockable hinged steel panels cover and protect name plate gauges and ignition switch (padlock included). Also includes engine compartment door lock and key.

Blue Star Accessories



Lifting Eye 195353For Fusion and Blue Star.



Running Gear 301246

For Fusion and Blue Star.
Compact and balanced, lightweight wheelbarrow-style running gear provides easy onsite mobility.

Bobcat and Trailblazer Accessories (Gas/LP)



Multi-Terrain Running Gear 301460

For Bobcat Air Pak. Includes two heavy-duty Never Flat™ 15-inch tires, two 8-inch rubber swivel casters and a heavy-duty handle. Recommended for all surfaces and applications

and is easy to move around the jobsite.



Multi-Terrain Running Gear 300913 Inner tubes 300914 Never Flat™ tires For gas/LP Bobcat and Trailblazer (except Air Pak models). Includes two heavy-duty 15-inch tires, two 8-inch rubber swivel casters and a heavy-duty

handle. Recommended for all surfaces and applications and is easy to move around the jobsite.



Off-Road Running Gear 300909 Inner tubes 300910 Never Flat™ tires For gas/LP Bobcat and Trailblazer (except Air Pak models). Includes four heavy-duty 15-inch tires and a rugged handle to provide maximum maneuverability.



Off-Road Running Gear with Protective Cage and Never Flat™ Tires 300912 For gas/LP Bobcat and Trailblazer (except Air Pak models). Running gear and rugged cage with cable holders protects your investment and is easy to

Prote Cabl 3009

Protective Cage with Cable Holders

move around the jobsite.

300921 For gas/LP Bobcat and Trailblazer (except Air Pak models).

300473 For Trailblazer 302 Air Pak.

Rugged cage with cable holders protects your investment. Works with Running Gear, Gas Cylinder Mounting Assembly or LP Tank Mounting Assembly.



Gas Cylinder Mounting Assembly 300918

For gas Bobcat and
Trailblazer (except Air Pak
models). Designed for
use with Running Gear,
Protective Cage, or by itself.
Includes base tray with bottle
bracket, vertical support rack
and safety chain.

Note: Not for use with LP Tank Mounting Assembly. Not recommended for use with Protective Cover.



Hose and LP Tank Mounting Assembly 300917

For LP Bobcat and Trailblazer. Designed for use with Running Gear, Protective Cage, or by itself. Includes bracket and clamp to mount 33- and 43-pound tanks horizontally, and hose with fittings to converter.

Note: Cannot be used with Gas Cylinder Mounting Assembly. Not recommended for use with Protective Cover.



Remote Oil Drain and Filter Kit 300923 Field

For gas Bobcat and Trailblazer (except Air Pak models). Front mount for Kohler engines makes servicing easy when engine drive is mounted in tight spots.

Bobcat and Trailblazer Accessories (Diesel)



All-Purpose Running Gear with Never Flat™ Tires 300477

For diesel Bobcat and Trailblazer. Includes two heavy-duty 15-inch tires, two 8-inch rubber swivel casters and a heavy-duty handle. Recommended for

all surfaces and applications and is easy to move around the jobsite.



Protective Cage with Cable Holders 195331

For diesel Bobcat and Trailblazer. Rugged cage with cable holders protects your investment. Works with Running Gear, or with trailer.

Note: Not for use with Protective Cover.

Generator Accessories



Twist Lock Adapter Cord 301489

For Fusion. L14-30R to NEMA 6-50R. Adapts engine drive 120/240-volt twist lock plug to common Millermatic and Spectrum 240-volt plug.





Female Receptacle

Full KVA Adapter Cord 300517

For Bobcat, Trailblazer and Big Blue models. NEMA 14-50P to NEMA 6-50R. Adapts engine drive 120/240-volt plug to common Millermatic and Spectrum 240-volt plug.



Full KVA Plug Kit

119172 1-phase, 120/240 V, 50 A plug (NEMA 14-50P). For Bobcat, Trailblazer and Big Blue models.

165963 3-phase, 480 V, 30 A plug (NEMA L16-30P). *For Bobcat 3 Phase*.

254140 3-phase, 240 V, 50 A plug (NEMA 15-50P). *For Big Blue 500 Pro/* 600 Series/800 Series.

Protective Covers



Protective covers (300919) and (195301) shown.

Protective Covers

Heavy-duty, water- and mildew-resistant covers protect and maintain the finish of the welder.

301245 For Fusion and Blue Star.

 $\textbf{301475} \ \ \textit{For Bobcat 200 Air Pak without} \ \textit{Running Gear}.$

301476 For Bobcat 200 Air Pak with Running Gear.

300919 For gas Bobcat and Trailblazer (except Air Paks) without Protective Cage or Running Gear.

300920 For gas Bobcat and Trailblazer (except Air Paks) with Protective Cage or Running Gear.

301099 For diesel Bobcat and Trailblazer without Protective Cage or Running Gear.

300379 For Trailblazer 302 Air Pak.

195301 For Big Blue 400 Pro/400 PipePro/450 Duo CST.

301495 For Big Blue 500 Pro/600 Pro with Kubota.

301113 For Big Blue 600 Air Pak/800 Series with Deutz.

· · · Accessories

Plasma Cutter Accessories

Automation Kits



Automation Kit
for Spectrum 625
X-TREME 301158
Upgrades quickconnect hand-held
torch packages
to add machine

torch capabilities.

Includes front panel with built-in remote control cable receptacle. Machine torches are NOT included in kits and must be ordered separately.



Automation kit (301157) shown.

Automation Kits for Spectrum 875 and 875 Auto-Line 301156 For Spectrum 875.

301157 For Spectrum 875 Auto-Line.

Upgrades hand-held torch packages to add machine torch capabilities. Automation kit for Spectrum 875 Auto-Line (301157) includes a remote pendant control for manual on/off. Machine torches are NOT included in kits and must be ordered separately.

Cables and Cable Covers



Flexible Work Cable 234838 20 ft. (6.1 m) 234930 50 ft. (15.2 m) Work cable with quick connect and heavy-duty clamp.



Cable Covers 239642 20 ft. (6.1 m) **231867** 25 ft. (7.6 m) **231868** 50 ft. (15.2 m)

Cutting Guides



Plasma Circle-Cutting Guides 253055

For XT30C/XT30/XT40/XT60 torches. Cut straight lines or circles up to 12 inches in diameter.



Suction/Magnetic Pivot Base 195979

Add this to your cutting guide for convenient attachment to all flat surfaces. The extended arm accommodates holes up to 30 inches in diameter.



Plasma Standoff
Roller Guide 253054
Helps maintain
recommended standoff
distance to maximize
cutting performance
and improve tip life.

Filters



In-Line Air Filter Kit 228926

For Spectrum 375 X-TREME/625 X-TREME/875/875 Auto-Line. Mounts to back of the plasma cutter. Includes male and female 1/4-inch NPT quick-disconnect fittings and hose for easy on/off connection. The replaceable filter element (228928) filters to .85 microns for removal of 99.9 percent of water, dirt and oil.



RTI Filter and Bracket 300491

For Spectrum 875/875 Auto-Line. Dryer will remove water, dirt and oil as small as one micron with 99.9 percent efficiency. Can be mounted on plasma cutter or on wall. Install as close as possible to point of air consumption. Replaceable filter element (212771).

Plugs and Cords

MVP™ Plugs



219258

219261

For 6-50P power cable (230/240 V, 50 A).

For 5-15P power cable (115/120 V, 15 A).

219259For 5-20P power cable (115/120 V, 20 A).

For Spectrum 375 X-TREME, Millermatic 211, Multimatic 200/215/220 AC/DC, Thunderbolt 160, Diversion, Syncrowave 210 and Fusion. Allows connection of machine to 115/120-volt or 230/240-volt receptacles without tools — just choose the plug that fits the receptacle.

MVP™ Adapters





Female Receptacle



254328

For connection to 6-50P receptacle (240 V, 50 A).



254330

For connection to 5-15P receptacle (120 V, 15 A).



254331

For connection to 5-20P receptacle (120 V. 20 A).

For Spectrum 625 X-TREME. Allows connection of machine to 120- or 240-volt receptacles without tools — just choose the adapter cord that fits the receptacle.





Full KVA Adapter Cord 300517

NEMA 14-50P to NEMA 6-50R. Adapts engine drive 120/240-volt plug to common Millermatic and Spectrum 240-volt plug.

230-Volt Extension Cord 770644

20-foot (6.1 m) NEMA 6-50P to NEMA 6-50R heavy-duty extension cord. 8-gauge cord has lighted ends that show power is on and a molded integrated strain relief.

Protective Covers



X-CASE 300184 For Spectrum 375 X-TREME/ 625 X-TREME.

Torches

See your Miller® distributor for complete information on the following XT plasma torches and their consumables:



Spectrum Plasma Cutter Hand-Held Torches

For Spectrum 375 X-TREME 249949 12 ft. (3.7 m) XT30 For Spectrum 625 X-TREME 260633 12 ft. (3.7 m) XT40

260635 20 ft. (6.1 m) XT40 For Spectrum 875 and 875 Auto-Line

249953 20 ft. (6.1 m) XT60 **249954** 50 ft. (15.2 m) XT60



Spectrum Plasma Cutter Machine Torches

For Spectrum 625 X-TREME

259305 25 ft. (7.6 m) long body XT40M **257462** 25 ft. (7.6 m) short body XT40M

For Spectrum 875 and 875 Auto-Line

 25 ft. (7.6 m) long body XT60M 50 ft. (15.2 m) long body XT60M 25 ft. (7.6 m) short body XT60M 50 ft. (15.2 m) short body XT60M



Each consumable kit includes a storage box.

Plasma Torch Consumable Kits

253520 For XT30 torch. Includes 5 electrodes, 5 tips, 1 swirl ring, 1 retaining cup, 1 o-ring and silicone grease. **253521** For XT40 torch. Includes 5 electrodes, 5 tips (40 A), 3 tips (30 A), 1 drag shield (40 A), 2 drag shields (30 A), 1 deflector, 1 o-ring, 1 swirl ring, 1 retaining cup, 1 gouge tip (40 A), 1 gouge shield and silicone grease.

256033 For XT60 torch. Includes 3 standard electrodes, 3 standard tips, 1 drag shield, 1 deflector, 1 o-ring, 1 swirl ring, 1 retaining cup, 1 gouge tip, 1 gouge shield and silicone grease.

127493 Empty consumable storage box.