

# Dynasty® 210 DX Models/Packages

## Build an Air-Cooled Package

Select desired stock number for each step.



907686  
Dynasty shown.



301311  
kit shown.

Step 1 • Select Dynasty		Step 2 • Select Contractor Kit	
Dynasty 210 DX	907686	A-150 TIG Torch and RFCS-14 HD Foot Control	301309
Dynasty 210 DX (CPS)	907686002	A-150 TIG Torch with RCCS-14 Fingertip Control	301311
<i>Note: For models without the Cooler Power Supply (CPS), the Coolmate 1.3 must be powered through an external 120-volt facility power.</i>		A-200 TIG Torch with RFCS-14 HD Foot Control	301549
		A-200 TIG Torch with RCCS-14 Fingertip Control	301550
Dynasty comes with adjustable shoulder strap, 8 ft. power cord (no plug), quick-reference guide and two 50 mm Dinse-style connectors.		See page 6 for kit contents.	

## Build a Water-Cooled Package

Select desired stock number for each step.



907686001  
Dynasty 210 DX  
TIGRunner® shown  
with four bottles  
of 043810  
Low-Conductivity  
Coolant.



301580 remote shown.



300185 kit shown.

Step 1 • Select Dynasty TIGRunner® and Coolant		Step 2 • Select Remote Control		Step 3 • Select Torch Kit	
Dynasty 210 DX (CPS) TIGRunner	907686001	Wireless Foot (recommended)	301580	W-250 Kit	300185
&		RFCS-14 HD Foot	194744	(recommended for 210 model)	
Low-Conductivity Coolant	043810	RCC-14 E/W Fingertip	151086	W-280 Kit	300990
(Must be ordered in quantities of four.)		RCCS-14 N/S Fingertip	043688		
		RMS-14 Pushbutton	187208		
		RMLS-14 Momentary/Maintained	129337		
		RHC-14 Hand	242211020		
		Wireless Hand	301582		
Dynasty TIGRunner comes with 8 ft. power cord (no plug), quick-reference guide, Coolmate™ 1.3 and Small Runner™ cart.		See page 7 for remote descriptions.		See page 6 for kit contents.	

## Preconfigured Water-Cooled Packages

Use a single stock number to order a complete preconfigured system.



951880  
package shown.

### Select Water-Cooled Complete Package

Dynasty 210 DX (CPS) Complete with Foot Control	951668
Dynasty 210 DX (CPS) Complete with Wireless Foot Control	951880

Comes with:

- 8 ft. power cord (no plug)
- Quick-reference guide
- Coolmate™ 1.3 300972
- Coolant (4 one-gallon bottles of 043810)
- Small Runner™ cart 301615
- Remote control 194744 (foot) **OR** remote control 301580 (wireless foot)
- W-250 torch kit 300185 (see page 6 for contents)

## Ordering Information

Equipment and Options	Stock No.	Description	Qty.	Price
Dynasty® 210 DX	907686	Auto-Line™ 120–480 V, 50/60 Hz, <b>CSA</b> . 8 ft. power cord		
Dynasty® 210 DX (CPS)	907686002	Auto-Line™ 120–480 V, 50/60 Hz, <b>CSA</b> . 8 ft. power cord		
Dynasty® 210 DX (CPS) International	907686003	Auto-Line™ 120–480 V, 50/60 Hz, <b>CE</b> . 8 ft. power cord		
<b>Water-Cooled Packages</b>				
Dynasty® 210 DX (CPS) TIGRunner®	907686001	Auto-Line™ 120–480 V, 50/60 Hz, <b>CSA</b> . 8 ft. power cord (Torch kit, accessories and coolant sold separately)		
Dynasty® 210 DX (CPS) Complete w/Foot Control	951668	Auto-Line™ 120–480 V, 50/60 Hz, <b>CSA</b> . 8 ft. power cord		
Dynasty® 210 DX (CPS) Complete with Wireless Foot Control	951880	Auto-Line™ 120–480 V, 50/60 Hz, <b>CSA</b> . 8 ft. power cord		
<b>Accessories</b>				
2-Wheel Trolley Cart	300971	For Dynasty/Maxstar 210 and 280 with or without Coolmate 1.3		
Small Runner™ Cart	301615	For Dynasty/Maxstar 210 and 280 with or without Coolmate 1.3		
Coolmate™ 1.3	300972	120 V, 60 Hz, <b>CSA</b> . <i>Requires coolant</i>		
Protective Cover	301382	For Dynasty 210/280 and Maxstar 280		
TIG Coolant (must be ordered in quantities of four)	043810	1-gallon plastic bottle. Protects against freezing to -37° Fahrenheit (-38°C) or boiling to 227° Fahrenheit (108°C)		
TIG Gloves		See page 6		
Memory Cards		See page 6		
<b>TIG Torches, Kits and Connectors</b>				
Air-Cooled Contractor Kits		See page 6		
Weldcraft™ A-150 (WP-17) TIG Torch	<b>WP-17-12-R</b> <b>WP-17-25-R</b>	12 ft. (3.7 m) cable. Requires <b>195378</b> connector 25 ft. (7.6 m) cable. Requires <b>195378</b> connector		
Weldcraft™ A-200 (WP-26) TIG Torch	<b>WP-26-12-R</b> <b>WP-26-25-R</b>	12 ft. (3.7 m) cable. Requires <b>195379</b> connector 25 ft. (7.6 m) cable. Requires <b>195379</b> connector		
Air-Cooled TIG Torch Connectors	<b>195378</b> <b>195379</b>	Connects all air-cooled Weldcraft™ torches (except A-200) to Dinse-style connector. A-80 (WP-24) torches require <b>24-5</b> connector Connects Weldcraft™ A-200 (WP-26) torch to Dinse-style connector		
Water-Cooled Torch Kits		See page 6		
Weldcraft™ W-225 Modular (WP-225) TIG Torch	<b>WP-225-12-R</b> <b>WP-225-25-R</b>	12 ft. (3.7 m) cable. Requires <b>195377</b> connector 25 ft. (7.6 m) cable. Requires <b>195377</b> connector		
Water-Cooled TIG Torch Connector	<b>195377</b>	Connects Weldcraft™ water-cooled torches to Dinse-style connector		
Tungsten		See page 7		
<b>Remote Controls</b>		See page 7		
<b>Educational Materials</b>		See page 7		

Date:

Total Quoted Price:

Distributed by:

